

ID :2009 Bailey Bridge at chainage 9.325 of UGT m/r \_\_\_\_\_

on Chainage 9.325 of Uttarkashi Ghansali Tilwara state highway

In District Uttarkashi Under PD Bhatwari Division

---

## Bridge Inventory Report

Division: PD Bhatwari

Data not-yet finalized

### General

Name of Division : 31

Revenue Block Name : 6

Chainage (at Mid Point) : 9.325

Road/ Segment Name : 98

Bridge Type : Motor Bridge High Level

Structure No : 9/13

Feature Intersected : Sada Gad

Name of Bridge : Bailey Bridge at chainage 9.325 of UGT m/r

Nearest Town : Uttarkashi

Latitude (Northing) : 30.70495700

Longitude (Easting) : 78.47534800

Construction Year : 2021

Inventory Year : 2022

### Geometric

Overall length (in meter) : 24.00

Total No of Span : 1

Maximum Span (in meter) : 24.00

Span Arrangement : 24.00

No of Lane : 1.000

Overall Width (m) : 5.700

Carriageway Width (m) : 4.250

RS Footpath Width (m) : 0.000

LS Footpath Width (m) : 0.000

Approach Width i/c Shoulders (m) : 5.950

Gradient (%age) : 0

Skew Angle (degree) : 0.00

Radius of Curve in Plan (if Any) : 0.00

### Design Data

HFL Highest Flood Level :

OFL Ordinary Flood Level :

LWL Low Water Level :

Design Velocity (m/Sec) :

Design Discharge (Cumecs) :

Soffit Level at Centre :

Road Level at Centre :

Design Scour Level at Pier :

Design Scour Level at Abutments :

Exposure Condition : Moderate

Seismic Importance factor : 0.0

Design Loading : Class B  
Load Rating : Class B  
Super-Structure  
Superstructure Type : Bailey  
Superstructure Material : Steel  
Wearing Coat Type : Not Provided  
Expansion Joint Type : Other  
Railing/Crash Barrier type : Steel rolled section  
Bearing type : other  
Sub-Structure  
Founding Strata : Rocky  
Abutment Foundation Type : Open  
Pier Foundation Type : NA  
No of Piers : 0  
Abutment Type : Stone Masonry  
Pier Type : NA  
Protection Work  
Bank Protection Left Side of Up-stream : Plum block  
Bank Protection Right Side of Up-stream : RR Wing Wall  
Bank Protection Left Side of Down-stream : no protection work provided  
Bank Protection Right Side of Down-stream : Plum block  
Floor Protection on Up-stream : no protection work provided  
Floor Protection on Down-stream : Plum block  
Treatment for Corrosion Protection (if any) : no special treatment provided  
final

Name of JE/AAE :

