

ID :1509 Local Nala \_ \_ \_ \_ \_

on Chainage 141.195 of Jyolikot Almora Karanprayag national highway

In District Almora Under NH Ranikhet Division

---

## Bridge Inventory Report

Division: NH Ranikhet

Data not-yet finalized

### General

Name of Division : 83

Revenue Block Name : 66

Chainage (at Mid Point) : 141.195

Road/ Segment Name : 12

Bridge Type : Motor Bridge High Level

Structure No : 142/6

Feature Intersected : Local Gadhera

Name of Bridge : Local Nala

Nearest Town : Dwarahat

Latitude (Northing) : 29.79188100

Longitude (Easting) : 79.42034200

Construction Year :

Inventory Year : 2020

### Geometric

Overall length (in meter) : 7.00

Total No of Span : 1

Maximum Span (in meter) : 6.00

Span Arrangement : 1X6.00

No of Lane : 1.000

Overall Width (m) : 12.000

Carriageway Width (m) : 11.500

RS Footpath Width (m) : 0.000

LS Footpath Width (m) : 0.000

Approach Width i/c Shoulders (m) : 7.500

Gradient (%age) : 0

Skew Angle (degree) : 0.00

Radius of Curve in Plan (if Any) : 0.00

### Design Data

HFL Highest Flood Level :

OFL Ordinary Flood Level :

LWL Low Water Level :

Design Velocity (m/Sec) :

Design Discharge (Cumecs) :

Soffit Level at Centre :

Road Level at Centre :

Design Scour Level at Pier :

Design Scour Level at Abutments :

Exposure Condition : Moderate

Seismic Importance factor : 0.0

Design Loading : Class A

Load Rating : NA

Super-Structure

Superstructure Type : Single/Multi-cell Box

Superstructure Material : Reinforced concrete

Wearing Coat Type : Bituminous Concrete

Expansion Joint Type : Not Provided

Railing/Crash Barrier type : Cast-in-situ concrete

Bearing type : Not Provided

Sub-Structure

Founding Strata : Rocky

Abutment Foundation Type : Open

Pier Foundation Type : NA

No of Piers : 0

Abutment Type : RCC Box type

Pier Type : NA

Protection Work

Bank Protection Left Side of Up-stream : no protection work provided

Bank Protection Right Side of Up-stream : no protection work provided

Bank Protection Left Side of Down-stream : no protection work provided

Bank Protection Right Side of Down-stream : no protection work provided

Floor Protection on Up-stream : no protection work provided

Floor Protection on Down-stream : no protection work provided

Treatment for Corrosion Protection (if any) : no special treatment provided

final

Name of JE/AAE : Er. Santosh Kumar (AAE)

