

ID :2147 30 m span Valley Bridge in ch. 1.500 \_ \_ \_ \_ \_

on Chainage 1.500 of Roorkee Laksar Balawali road to Kalsia link road

In District Haridwar Under CD Laksar Division

---

## Bridge Inventory Report

Division: CD Laksar

Data not-yet finalized

### General

Name of Division : 129

Revenue Block Name : 95

Chainage (at Mid Point) : 1.500

Road/ Segment Name : 2566

Bridge Type : Motor Bridge High Level

Structure No : 1/1

Feature Intersected : Ban Ganga

Name of Bridge : 30 m span Valley Bridge in ch. 1.500

Nearest Town : Raisi

Latitude (Northing) : 29.67000000

Longitude (Easting) : 78.06000000

Construction Year : 2013

Inventory Year : 2022

### Geometric

Overall length (in meter) : 30.50

Total No of Span : 1

Maximum Span (in meter) : 30.00

Span Arrangement : 1x30

No of Lane : 1.000

Overall Width (m) : 6.000

Carriageway Width (m) : 4.000

RS Footpath Width (m) : 0.000

LS Footpath Width (m) : 0.000

Approach Width i/c Shoulders (m) : 7.500

Gradient (%age) : 0

Skew Angle (degree) : 0.00

Radius of Curve in Plan (if Any) : 0.00

### Design Data

HFL Highest Flood Level :

OFL Ordinary Flood Level :

LWL Low Water Level :

Design Velocity (m/Sec) :

Design Discharge (Cumecs) :

Soffit Level at Centre :

Road Level at Centre :

Design Scour Level at Pier :

Design Scour Level at Abutments :

Exposure Condition : Moderate

Seismic Importance factor : 1.0

Design Loading : Class B

Load Rating : Class B

Super-Structure

Superstructure Type : Bailey

Superstructure Material : Steel

Wearing Coat Type : Other

Expansion Joint Type : Not Provided

Railing/Crash Barrier type : Steel rolled section

Bearing type : Roller & Rocker

Sub-Structure

Founding Strata : Sandy

Abutment Foundation Type : Raft

Pier Foundation Type : Raft

No of Piers : 0

Abutment Type : RCC counterfort type

Pier Type : other

Protection Work

Bank Protection Left Side of Up-stream : no protection work provided

Bank Protection Right Side of Up-stream : no protection work provided

Bank Protection Left Side of Down-stream : no protection work provided

Bank Protection Right Side of Down-stream : no protection work provided

Floor Protection on Up-stream : no protection work provided

Floor Protection on Down-stream : no protection work provided

Treatment for Corrosion Protection (if any) : no special treatment provided

final

Name of JE/AAE : Pardeep kumar /Lalit Mohan Singh

