

ID :359 Dwarsoan Kakdighat motor Road Bridge 01 \_\_\_\_\_

on Chainage 0.240 of Dwarsoan Kakrighat motor road( From Dwarsoan)

In District Almora Under PD Almora Division

---

## Bridge Inventory Report

Division: PD Almora

Data not-yet finalized

### General

Name of Division : 1

Revenue Block Name : 64

Chainage (at Mid Point) : 0.240

Road/ Segment Name : 566

Bridge Type : Motor Bridge High Level

Structure No : 1/1

Feature Intersected : Kosi River

Name of Bridge : Dwarsoan Kakdighat motor Road Bridge 01

Nearest Town : Kakdighat

Latitude (Northing) : 29.54597200

Longitude (Easting) : 79.53377800

Construction Year : 1984

Inventory Year : 2020

### Geometric

Overall length (in meter) : 56.00

Total No of Span : 1

Maximum Span (in meter) : 56.00

Span Arragment : 1x56.00

No of Lane : 1.000

Overall Width (m) : 5.250

Carriageway Width (m) : 4.250

RS Footpath Width (m) : 0.000

LS Footpath Width (m) : 0.000

Approch Width i/c Shoulders (m) : 5.950

Gradient (%age) : 0

Skew Angle (degree) : 0.00

Radius of Curve in Plan (if Any) : 0.00

### Design Data

HFL Highest Flood Level : 988.000

OFL Ordinary Flood Level : 981.000

LWL Low Water Level : 980.000

Design Velocity (m/Sec) : 0.00

Design Discharge (Cumecs) : 0.00

Soffit Level at Centre : 0.000

Road Level at Centre : 0.000

Design Scour Level at Pier : 0.000

Design Scour Level at Abutments : 0.000

Exposure Condition : Mild

Seismic Importance factor : 1.0

Design Loading : NA

Load Rating : NA

Super-Structure

Superstructure Type : Solid slab

Superstructure Material : Reinforced concrete

Wearing Coat Type : Cement Concrete

Expansion Joint Type : Single Strip/Box Seal Joint

Railing/Crash Barrier type : Tubular steel

Bearing type : Roller & Rocker

Sub-Structure

Founding Strata : Rocky

Abutment Foundation Type : Raft

Pier Foundation Type : NA

No of Piers : 0

Abutment Type : Stone Masonry

Pier Type : NA

Protection Work

Bank Protection Left Side of Up-stream : no protection work provided

Bank Protection Right Side of Up-stream : no protection work provided

Bank Protection Left Side of Down-stream : no protection work provided

Bank Protection Right Side of Down-stream : no protection work provided

Floor Protection on Up-stream : no protection work provided

Floor Protection on Down-stream : no protection work provided

Treatment for Corrosion Protection (if any) : no special treatment provided

final

Name of JE/AAE : Er. Pradeep Joshi

