

ID :690 Arch Bridge OF IRRIGATION CANAL at Paheniya shiripur Bichuva Road _____

on Chainage 2.000 of Paheniya Shripur Bichuwa road

In District Udham Singh Nagar Under CD Khatima Division

Bridge Inventory Report

Division: CD Khatima

Data not-yet finalized

General

Name of Division : 24

Revenue Block Name : 89

Chainage (at Mid Point) : 2.000

Road/ Segment Name : 6254

Bridge Type : Motor Bridge High Level

Structure No : 1/2

Feature Intersected : Devha River

Name of Bridge : Arch Bridge OF IRRIGATION CANAL at Paheniya shiripur Bichuva Road

Nearest Town : KHATIMA

Latitude (Northing) : 28.94361100

Longitude (Easting) : 79.93222200

Construction Year : 1976

Inventory Year : 2021

Geometric

Overall length (in meter) : 24.00

Total No of Span : 3

Maximum Span (in meter) : 24.00

Span Arrangement : 3*8

No of Lane : 1.000

Overall Width (m) : 3.650

Carriageway Width (m) : 3.650

RS Footpath Width (m) : 0.000

LS Footpath Width (m) : 0.000

Approach Width i/c Shoulders (m) : 9.000

Gradient (%age) : 0

Skew Angle (degree) : 0.00

Radius of Curve in Plan (if Any) : 0.00

Design Data

HFL Highest Flood Level :

OFL Ordinary Flood Level :

LWL Low Water Level :

Design Velocity (m/Sec) :

Design Discharge (Cumecs) :

Soffit Level at Centre :

Road Level at Centre :

Design Scour Level at Pier :

Design Scour Level at Abutments :

Exposure Condition : Moderate

Seismic Importance factor : 1.0

Design Loading : Class B

Load Rating : Class B

Super-Structure

Superstructure Type : Arch

Superstructure Material : Masonry

Wearing Coat Type : Bituminous Concrete

Expansion Joint Type : Not Provided

Railing/Crash Barrier type : other

Bearing type : Not Provided

Sub-Structure

Founding Strata : Sandy

Abutment Foundation Type : other

Pier Foundation Type : other

No of Piers : 3

Abutment Type : Brick Masonry

Pier Type : Brick Masonry

Protection Work

Bank Protection Left Side of Up-stream : no protection work provided

Bank Protection Right Side of Up-stream : no protection work provided

Bank Protection Left Side of Down-stream : no protection work provided

Bank Protection Right Side of Down-stream : no protection work provided

Floor Protection on Up-stream : no protection work provided

Floor Protection on Down-stream : no protection work provided

Treatment for Corrosion Protection (if any) : no special treatment provided

final

Name of JE/AAE : ER. A. K. SATSANGI

